




L/B MR. ALAN with new sponsons - 127 ft legs, top of pad 5-9" abv keel
Level trim/heel, 0, 0, 0 at CL Bow Keel, Salt Water




L/B MR. ALAN with new sponsons - 127 ft legs, top of pad 5-9" abv keel
Level trim/heel, 0, 0, 0 at CL Bow Keel, Salt Water




L/B MR. ALAN with new sponsons - 127 ft legs, top of pad 5'-9" abv keel
Level trim/heel, 0, 0, 0 at CL Bow Keel, Salt Water




L/B MR. ALAN with new sponsons - 127 ft legs, top of pad 5-9" abv keel
Level trim/heel, 0, 0, 0 at CL Bow Keel, Salt Water




L/B MR. ALAN with new sponsons - 127 ft legs, top of pad 3.75 from keel
Level trim/heel, 0, 0, 0 at CL Bow Keel, Salt Water




L/B MR. ALAN with new sponsons - 127 ft legs, top of pad 1.75 from keel
Level trim/heel, 0, 0, 0 at CL Bow Keel, Salt Water



L/B MR. ALAN with new sponsons - 127 ft legs, top of pad -0.25 from keel
Level trim/heel, 0, 0, 0 at CL Bow Keel, Salt Water



L/B MR. ALAN with new sponsons - 127 ft legs, top of pad -2.25 from keel
Level trim/heel, 0, 0, 0 at CL Bow Keel, Salt Water



L/B MR. ALAN with new sponsons - 127 ft legs, top of pad -4.25 from keel
Level trim/heel, 0, 0, 0 at CL Bow Keel, Salt Water

